



Project Review Reimbursable Agreement

Project Review Reimbursable Agreement		Applicant or Local Agency Pacific County Emergency Management Agency	
Agreement Number J D1719		Billing Address PO Box 1143 South Bend, WA 98586	
Fed ID/SWW/Payee # 91-6001356			
Region Southwest		Contact Email smcdougall@co.pacific.wa.us	
Contact Name Scott McDougall, PCEMA Director		Contact Phone 360-875-9338	
Estimated Costs This estimate is based on the best available information to date and includes WSDOT's Indirect Cost Rate \$7,200.00*		Surety Amount \$ <input checked="" type="checkbox"/> Not Applicable	
SR See Attachment A	MP See Attachment A	Project Name Pacific County Tsunami Sign Replacement	
Detailed Description of Work by WSDOT <input type="checkbox"/> Project Review <input type="checkbox"/> Inspection <input checked="" type="checkbox"/> Other Replace 60 existing Tsunami Signs and 60 directional arrow signs throughout Pacific County. Sign list, including locations, is detailed on Attachment A and sign description is shown on Attachment B. All signs will be provided by the Local Agency at Local Agency expense. Labor, equipment, new sign posts (5), and associated hardware will be provided by WSDOT at Local Agency expense. Upon installation, WSDOT will maintain the signs (60), arrows (60), and posts (5) provided under this Agreement. *The current Indirect Cost Rate is 12.67% and is valid through June 30, 2023.			

This AGREEMENT is entered into by and between the Washington State Department of Transportation, hereinafter "WSDOT," and the above named "APPLICANT OR LOCAL AGENCY," hereinafter the "ENTITY;" herein after referred to individually as the "Party" and collectively as the "Parties."

Recitals

1. The ENTITY has requested WSDOT to perform the above described work, and WSDOT is authorized and willing to perform the work.
2. The ENTITY is responsible for the costs associated with the work.

NOW THEREFORE, pursuant to the terms, conditions and performances contained herein and/or attached hereto, and by this reference made a part of this Agreement,

It Is Mutually Agreed to As Follows:

1. GENERAL

- 1.1 The WSDOT agrees to perform the above described work requested by the ENTITY, using state labor, equipment and materials.
- 1.2 To secure payment of the potential costs incurred in the review process, WSDOT requests that a Surety Amount in the form of Bond, Assignment of Escrow, Certificate of Deposit, Irrevocable Letter of Credit, Check or Money Order in the amount listed above accompany the endorsed original copy of this Agreement.
- 1.3 All WSDOT reviews, and/or inspections provided by WSDOT are solely for the benefit of WSDOT and not for the ENTITY or any other third party.

2. PAYMENT

- 2.1 The ENTITY, in consideration of the faithful performance of the work by WSDOT, agrees to reimburse WSDOT for the actual direct and related indirect costs associated with the work, including WSDOT's current administrative indirect cost rate.
- 2.2 The ENTITY agrees to make payment for the work by WSDOT within thirty (30) calendar days from the date of a state invoice.
- 2.3 The ENTITY agrees that if it fails to make payment within thirty (30) calendar days of the invoice, the WSDOT may charge interest in accordance with RCW 43.17.240 and may elect to send the outstanding invoice(s) to a WSDOT contracted collection agency resulting in the assessment of additional fees and/or penalties.
- 2.4 Upon payment of all WSDOT invoices by ENTITY, WSDOT will release rights of remaining Surety Amount.

3. INCREASE IN COST

- 3.1 The Parties agree that the estimated cost of the work may be exceeded by up to twenty-five (25) percent. In the event costs exceed the estimated costs by more than twenty-five (25) percent the Parties agree to modify the estimated cost of work by written amendment, signed by both Parties.

4. ASSIGNMENT

- 4.1 This Agreement, and any claim arising under this Agreement, shall not be assignable or delegable by either Party, either in whole or in part.

5. INDEMNIFICATION

- 5.1 The ENTITY shall defend, protect and hold harmless WSDOT, its officers, officials, employees, and/or agents from and against all claims, suits or actions arising from the negligent acts or omissions of ENTITY, its officers, officials, employees, assigns, contractors, sub-contractors, tenants, sub-tenants, licensees, invitees and/or agents while performing under the terms of this Agreement. This defense and indemnity obligation shall not include such claims, actions, costs, damages, or expenses which may be caused by the sole negligence of WSDOT, its officers, officials, employees, contractors, sub-contractors and/or agents; provided, however, that if the claims, suits or actions are caused by or result from the concurrent negligence of (a) WSDOT, its officers, officials, agents, contractors, sub-contractors or employees and (b) the ENTITY, its officers, officials, employees, assigns, contractors, sub-contractors, tenants, sub-tenants, licensees, invitees and/or agents, or involves those actions covered by RCW 4.24.115, this indemnity provision shall be valid and enforceable only to the extent of the negligence of the ENTITY or its officers, officials, employees, assigns, contractors, sub-contractors, tenants, sub-tenants, licensees, invitees and/or agents. ENTITY specifically assumes potential liability for the actions brought by ENTITY'S employees and solely for the purposes of this indemnification and defense, ENTITY specifically waives any immunity it may be afforded in connection with such claims under the State industrial insurance law, Title 51 RCW. ENTITY recognizes that this waiver was the subject of mutual negotiations.

This indemnification and waiver shall survive the termination of this Agreement.

6. AMENDMENT

- 6.1 This Agreement may be amended by the mutual agreement of the Parties. Such amendments shall not be binding unless they are in writing and signed by persons authorized to bind each of the Parties.

7. TERMINATION

- 7.1 Either Party may terminate this Agreement, with or without cause, by providing written notice to the other of such termination and specifying the effective date thereof at least thirty (30) calendar days before the effective date of such termination. The ENTITY will reimburse WSDOT for all charges up to the date of termination.

8. DISPUTES

- 8.1 The Parties shall work collaboratively to resolve disputes and issues arising out of, or related to this Agreement. Disagreements shall be resolved promptly and at the lowest level of hierarchy.

8.2 In the event that a dispute arises under this Agreement which cannot be resolved by the parties as outlined in Section 8.1, the dispute will be settled in the following manner: Each Party will appoint a member to a dispute board. The members so appointed will jointly appoint a third member to the dispute board who is not employed by or affiliated in any way with either Party. The dispute board will evaluate the facts, contract terms, and applicable statutes and rules and make a determination of the dispute. The determination of the dispute board will be final and binding on the Parties. Any costs associated with appointing the third member will be equally shared between the Parties. Each Party shall be responsible for its own costs, including attorneys fees.

8.3 The Parties agree that any legal action to enforce any right or obligation under this Agreement may only be brought in Thurston County Superior Court.

9. TERM OF AGREEMENT

9.1 The term of the Agreement shall begin upon the date of execution and shall remain in effect until WSDOT has completed the above described work and the ENTITY has made full payment, whichever comes last, unless modified according to Section 6, "AMENDMENT," above.

IN WITNESS WHEREOF, the Parties hereto have executed this Agreement as of the date last signed by the PARTIES below.

REQUESTING ENTITY	WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
By: _____	By: _____
Printed: <u>Scott McDougall</u>	Printed: <u>LisaRene Schilperoort</u>
Title: <u>PCEMA Director</u>	Title: <u>SWR Traffic Engineer</u>
Date: _____	Date: _____

**JD1719 Attachment A
Tsunami Evacuation Route Sign List**

Sign ID No.	Region	Maint. Area	SR	MP	Special MP	Road Location	Traffic Direction	Sort Order	Fab Number	Sign Message	Road Side	Width (Inches)	Height (Inches)	Last Update Date	Install Date	Sign Notes
176276	Southwest	3	6	0.04	0	ML	EB	1	125-101	Tsunami Evacuation Route	R	24	24	4/9/2020	9/17/1997	
176277	Southwest	3	6	0.04	0	ML	EB	2	D9-401	ARROW 0	R	6	24	4/9/2020	9/17/1997	
181777	Southwest	3	100	0.9	0	ML	EB	1	125-101	Tsunami Evacuation Route	R	24	24	6/28/2019	10/24/2005	Fab 05.
181778	Southwest	3	100	0.9	0	ML	EB	2	D9-401	arrow 0	R	6	24	6/28/2019	10/24/2005	Fab 05.
232038	Southwest	3	100	2.95	0.499	SP	WB	1	125-101	Tsunami Evacuation Route	L	24	24	4/8/2020	1/1/2006	Fab date 06
232039	Southwest	3	100	2.95	0.499	SP	WB	2	D9-401	Arrow 270	L	21	15	4/8/2020	1/1/2006	Fab date 12
181787	Southwest	3	101	2.94	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/20/2020	3/24/2015	Fab 09
209538	Southwest	3	101	2.94	0	ML	NB	2	D9-401	arrow 270	R	24	6	4/20/2020	1/1/2012	Fab date 12
176261	Southwest	3	101	3.04	0	ML	SB	2	125-101	Tsunami Evacuation Route	L	24	24	4/28/2020	9/8/2011	Fab date 10 MISSING FROM FIELD REVIEW
181788	Southwest	3	101	3.04	0	ML	SB	3	D9-401	arrow 90	L	24	6	4/28/2020	9/17/2003	Fab date 03 MISSING FROM FIELD REVIEW
181789	Southwest	3	101	9.41	0.56	AR	NB	1	125-101	Tsunami Evacuation Route	R	24	24	10/13/2003	10/13/2003	Fab 02.
174863	Southwest	3	101	11.201	0	ML	NB	2	D9-401	ARROW 90	R	24	6	4/22/2020	7/9/2005	Fab 05
232595	Southwest	3	101	11.201	0	ML	NB	2	D9-401	Arrow 90	R	24	6	4/22/2020	1/1/2005	Fab date 05
181836	Southwest	3	101	11.33	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/22/2020	10/15/2003	
181837	Southwest	3	101	11.33	0	ML	NB	2	D9-401	ARROW 90	R	24	6	4/22/2020	10/15/2003	
181898	Southwest	3	101	11.385	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	10/16/2013	Fab 13
181899	Southwest	3	101	11.385	0	ML	SB	2	D9-401	ARROW 270	L	24	6	4/29/2020	10/16/2013	Fab 13
174864	Southwest	3	101	11.5	0	ML	NB	3	125-101	Tsunami Evacuation Route	R	24	24	4/22/2020	11/14/2005	Fab 05.
195189	Southwest	3	101	11.5	0	ML	NB	4	D9-401	ARROW 0	R	6	24	4/22/2020	11/14/2005	Fab 05.
181892	Southwest	3	101	11.84	0	ML	NB	3	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	10/16/2003	Back to Back
181893	Southwest	3	101	11.84	0	ML	NB	4	D9-401	arrow 90	L	24	6	4/29/2020	10/16/2003	Back to Back
174886	Southwest	3	101	11.84	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	7/9/2002	Back to Back
181891	Southwest	3	101	11.84	0	ML	SB	2	D9-401	ARROW 270	L	24	6	4/29/2020	10/16/2003	Fab date 99
174865	Southwest	3	101	12.83	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/22/2020	7/9/1999	Fab date 05 MISSING FROM ORIGINAL LIST
153140	Southwest	3	101	12.83	0	ML	NB	2	D9-401	ARROW 270	R	24	6	4/29/2020	10/16/2005	Fab date 05
174885	Southwest	3	101	12.92	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	7/9/2005	Fab date 05
176249	Southwest	3	101	12.92	0	ML	SB	2	D9-401	ARROW 90	L	24	6	4/29/2020	10/16/2005	Fab date 05
182251	Southwest	3	101	13.89	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/22/2020	11/12/1999	Fab date 99
182252	Southwest	3	101	13.89	0	ML	NB	2	D9-401	ARROW 0	R	24	6	4/22/2020	11/12/1999	Fab date 99
174869	Southwest	3	101	15.67	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/22/2020	2/22/2017	Fab 16
191005	Southwest	3	101	15.67	0	ML	NB	2	D9-401	arrow 0	R	6	24	4/23/2020	1/1/2003	Fab date 03 MISSING FROM ORIGINAL LIST
239389	Southwest	3	101	26.62	0	ML	SB	3	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	1/1/2007	Fab date 07 BACK TO BACK W/ GOV'T RD STOP
174881	Southwest	3	101	34.345	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	10/15/1999	Fab date 99
181845	Southwest	3	101	34.345	0	ML	NB	2	D9-401	ARROW 90	R	24	6	4/23/2020	10/15/1999	Fab date 99
174880	Southwest	3	101	34.5	0	ML	SB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	7/9/2003	Fab date 03
176252	Southwest	3	101	34.5	0	ML	SB	2	D9-401	ARROW 270	L	24	6	4/23/2020	9/17/2003	Fab date 03
181847	Southwest	3	101	35.551	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	3/3/2005	Fab date 05
181846	Southwest	3	101	35.551	0	ML	NB	2	D9-401	ARROW 90	R	24	24	4/23/2020	3/3/2005	Fab date 05
176256	Southwest	3	101	35.88	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/23/2020	9/17/2002	
176257	Southwest	3	101	35.88	0	ML	SB	2	D9-401	ARROW 270	L	24	6	4/23/2020	9/17/2002	
181848	Southwest	3	101	38.25	0	ML	NB	3	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	10/15/2003	Back to Back Fab date 03
181849	Southwest	3	101	38.25	0	ML	NB	4	D9-401	ARROW 90	L	24	6	4/29/2020	10/15/2003	Back to Back Fab date 03

**JD1719 Attachment A
Tsunami Evacuation Route Sign List**

Sign ID No.	Region	Maint. Area	SR	MP	Special MP	Road Location	Traffic Direction	Sort Order	Fab Number	Sign Message	Road Side	Width (Inches)	Height (Inches)	Last Update Date	Install Date	Sign Notes
176254	Southwest	3	101	38.25	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	9/17/2003	Fab date 03
176255	Southwest	3	101	38.25	0	ML	SB	2	09-401	ARROW 270	R	24	6	4/29/2020	9/17/2003	Fab date 03
181850	Southwest	3	101	41.49	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	9/20/2007	FAB 05.
181851	Southwest	3	101	41.49	0	ML	NB	2	09-401	ARROW 90	R	24	6	4/23/2020	9/20/2007	FAB 05.
176227	Southwest	3	101	41.6	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	9/16/2002	
176228	Southwest	3	101	41.6	0	ML	SB	2	09-401	ARROW SIGN 0	L	24	6	4/29/2020	9/16/2002	
181852	Southwest	3	101	42.361	0	ML	NB	3	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	10/15/1999	Fab date 99. Facing Bay Center Dyke RD.
181853	Southwest	3	101	42.361	0	ML	NB	4	09-401	ARROW 90	R	24	6	4/23/2020	10/15/1999	Fab date 99. Facing Bay Center Dyke RD.
176224	Southwest	3	101	42.75	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	4/18/2007	Fab 05.
176225	Southwest	3	101	42.75	0	ML	NB	2	09-401	ARROW SIGN 90	R	24	6	4/23/2020	4/18/2007	Fab 05.
181888	Southwest	3	101	42.93	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	10/16/2003	
181889	Southwest	3	101	42.93	0	ML	SB	2	09-401	ARROW 270	L	48	18	4/29/2020	10/16/2003	
153459	Southwest	3	101	53.13	0	ML	NB	1	125-101	TSUNAMI EVACUATION ROUT	R	24	24	4/23/2020	1/1/2003	Fab date 03
176219	Southwest	3	101	53.13	0	ML	NB	2	09-401	arrow 0	R	6	24	4/23/2020	1/1/2003	Under tsunami sign Fab date 03
176221	Southwest	3	101	53.95	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/23/2020	6/5/2008	Fab 06.
181886	Southwest	3	101	53.95	0	ML	NB	2	09-401	ARROW 90	R	21	15	4/23/2020	6/5/2008	Fab 07.
181887	Southwest	3	101	54.02	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	10/16/2003	
182206	Southwest	3	101	56.15	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/27/2020	11/10/2003	
182207	Southwest	3	101	56.15	0	ML	NB	2	09-401	ARROW 90	R	24	6	4/27/2020	11/10/2003	
182239	Southwest	3	101	56.23	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	11/10/2003	
182240	Southwest	3	101	56.23	0	ML	SB	2	09-401	ARROW 270	L	24	24	4/29/2020	11/10/2003	
182210	Southwest	3	101	57.95	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/21/2020	11/10/1997	Fab date 97
182211	Southwest	3	101	57.95	0	ML	NB	2	09-401	arrow 90	R	24	6	4/27/2020	11/10/1997	Fab date 97
181862	Southwest	3	101	58.149	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/29/2020	7/31/2008	Fab date 06.
181863	Southwest	3	101	58.149	0	ML	SB	2	09-401	ARROW 270	L	24	12	4/29/2020	7/31/2008	Fab date 08.
181098	Southwest	3	101	59.33	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/21/2020	10/15/2003	
181857	Southwest	3	101	59.33	0	ML	NB	2	09-401	ARROW 90	R	24	6	4/27/2020	10/15/2003	
181932	Southwest	3	103	1.05	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	5/21/2020	10/16/2005	Fab 05
181933	Southwest	3	103	2.38	0	ML	SB	2	09-401	ARROW 0	L	24	6	5/21/2020	10/16/2003	Fab 03
181974	Southwest	3	103	2.38	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	5/20/2020	4/19/2007	Fab date 05
187404	Southwest	3	103	2.576	0	ML	NB	2	09-401	ARROW 90	R	24	6	5/20/2020	4/19/2007	Fab date 05.
187405	Southwest	3	103	2.576	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	5/28/2020	1/6/1997	Fab date 97
187406	Southwest	3	103	2.576	0	ML	SB	2	09-401	arrow 270	L	24	6	5/28/2020	1/6/1997	Fab date 97
181912	Southwest	3	103	4.405	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	7/8/2019	9/15/2005	Fab date 05
181910	Southwest	3	103	4.405	0	ML	NB	2	09-401	ARROW 90	R	24	6	7/8/2019	10/16/2003	Fab date 05
181928	Southwest	3	103	4.48	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	3/12/2018	10/16/1999	Fab date 18
181929	Southwest	3	103	4.48	0	ML	SB	2	09-401	ARROW 270	L	24	9	3/12/2018	10/16/1999	Fab date 17
181976	Southwest	3	103	6.57	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/8/2019	1/1/1999	Fab dae 99
181977	Southwest	3	103	6.57	0	ML	SB	2	09-401	ARROW 0	L	24	6	7/8/2019	1/1/1999	Fab dae 99
181924	Southwest	3	103	9.21	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/11/2019	2/11/2009	Fab 09.
181925	Southwest	3	103	9.21	0	ML	SB	2	09-401	ARROW 0	L	24	18	7/11/2019	2/11/2009	Fab 09.
181922	Southwest	3	103	11.06	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/12/2019	10/16/2000	

**JD1719 Attachment A
Tsunami Evacuation Route Sign List**

Sign ID No.	Region	Maint. Area	SR	MP	Special MP	Road Location	Traffic Direction	Sort Order	Fab Number	Sign Message	Road Side	Width (Inches)	Height (Inches)	Last Update Date	Install Date	Sign Notes
181973	Southwest	3	103	11.06	0	ML	SB	2	D9-401	ARROW 0	L	24	6	7/17/2019	10/16/2000	
176045	Southwest	3	103	11.29	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	3/7/2018	9/5/1999	Fab Date 18
193152	Southwest	3	103	11.29	0	ML	NB	2	D9-401	arrow 90	R	24	6	3/7/2018	8/10/1999	Fab Date 18
181920	Southwest	3	103	11.47	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/17/2019	10/16/1999	Fab Date 99
181921	Southwest	3	103	11.47	0	ML	SB	2	D9-401	ARROW 270	L	24	6	7/17/2019	10/16/1999	Fab Date 99
181915	Southwest	3	103	13.35	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	3/12/2018	12/13/2005	Fab 18
181916	Southwest	3	103	13.35	0	ML	NB	2	D9-401	ARROW 0	R	24	6	3/12/2018	12/13/2005	Fab 17
187406	Southwest	3	103	14.84	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	7/17/2019	1/6/2005	Fab date 2003
187407	Southwest	3	103	14.84	0	ML	NB	2	D9-401	arrow 270	R	24	6	7/17/2019	1/6/2005	Fab date 2003
187408	Southwest	3	103	14.92	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/17/2019	1/6/2005	Fab date 2003
187409	Southwest	3	103	14.92	0	ML	SB	2	D9-401	arrow 90	L	24	6	7/17/2019	1/6/2005	Fab date 2003
187410	Southwest	3	103	15.61	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	3/12/2018	1/6/2005	Fab date 2018
187411	Southwest	3	103	15.61	0	ML	SB	2	D9-401	arrow 90	L	21	15	3/12/2018	1/6/2005	Fab date 2010
181918	Southwest	3	103	15.95	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	7/17/2019	4/12/2011	Fab 10.
181919	Southwest	3	103	15.95	0	ML	SB	2	D9-401	ARROW 90	L	24	12	7/17/2019	4/12/2011	Fab 10.
193541	Southwest	3	105	11.52	0	ML	NB	3	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	8/17/2010	Back to Back Fab date 10
193542	Southwest	3	105	11.52	0	ML	NB	4	D9-401	arrow 90	L	21	10	4/9/2020	8/18/2006	Back to Back Fab date 06
176275	Southwest	3	105	11.52	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	8/18/2010	Back to Back Fab date 10
176274	Southwest	3	105	11.52	0	ML	SB	2	D9-401	arrow 270	L	21	10	4/9/2020	8/18/2010	Back to Back Fab date 10
200737	Southwest	3	105	18.26	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/8/2020	6/27/2006	Fab 05. Back to back w/ south bound.
200739	Southwest	3	105	18.26	0	ML	NB	2	D9-401	arrow 90	R	24	6	4/8/2020	6/27/2006	Fab 06. Back to back w/ arrow 270.
200738	Southwest	3	105	18.26	0	ML	SB	3	125-101	Tsunami Evacuation Route	R	24	24	4/8/2020	6/27/2006	Fab 05. Back to back w/ North bound.
200740	Southwest	3	105	18.26	0	ML	SB	4	D9-401	arrow 270	R	24	6	4/8/2020	6/27/2006	Fab 06. Back to back w/ arrow 90.
176272	Southwest	3	105	18.41	0	ML	SB	2	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	9/17/1997	Fab date 97. Under mileage info., Left Leg.
176273	Southwest	3	105	18.41	0	ML	SB	3	D9-401	arrow 90	L	6	24	4/9/2020	9/17/1997	Fab date 97. Under mileage info., Left Leg.
193544	Southwest	3	105	18.64	0	ML	SB	3	D9-401	arrow 90	L	24	6	4/9/2020	8/18/2005	Fab 06.
200163	Southwest	3	105	18.95	0	ML	NB	1	125-101	Tsunami Evacuation Route	R	24	24	4/8/2020	5/30/2006	Fab 06.
200164	Southwest	3	105	18.95	0	ML	NB	2	D9-401	arrow 90	R	24	6	4/8/2020	5/30/2006	Fab 06.
200166	Southwest	3	105	19.1	0	ML	SB	2	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	8/20/2009	Fab 09
200165	Southwest	3	105	19.1	0	ML	SB	3	D9-401	ARROW 270	L	24	6	4/9/2020	5/30/2006	Fab 06.
176269	Southwest	3	105	21.21	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	9/17/2012	Fab 12.
176270	Southwest	3	105	21.21	0	ML	SB	2	D9-401	ARROW 0	L	24	6	4/9/2020	9/17/2002	Fab date ?
176267	Southwest	3	105	23.62	0	ML	SB	1	125-101	Tsunami Evacuation Route	L	24	24	4/9/2020	9/17/2002	
176268	Southwest	3	105	23.62	0	ML	SB	2	D9-401	ARROW 0	L	24	6	4/9/2020	9/17/2002	

JD1719 Attachment B
Tsunami Evacuation Route Sign Description

